6E3051	B.Tech Mechan 6ME3	VI Sem. M nical Engg. Manufactu	1.7 5 . 28.4	Exam.	echnology	
Tim	e:3 Hours			Ma	ximum M	arks: 80
5) 10	. 1				Passing M	arks : 24
Instr	uctions to C					**************************************
		any five quest tion carry equ				84
		necessary. Ai				
2		d clearly.	.,	,	0	
e e e e e e e e e e e e e e e e e e e		quantities use	d/ calculate	ed must be	stated cler	ly.
	of followinged in form No	supporting man. 205)	aterial is per	mitted du	ring examin	ation. (Men-
1	ľ	Vil	2		Nil	
	d d		Unit-l		6 II	
1.	100	s various princ nts with neat sl	- 4	nping and	explain any t	wo clamping
92 10 02		n various part se of a setting		ng fixture v	with neat ske	etch. What is 8
?	e e		Or	2 5		0.
1.	N = N	draw drill jigs in figures sho		rill jigs for b)	i.	[8+8]
ŝi.	•	Drii 08				Drill \$6 1 (4 No.)
			\$ 20 Pre-machined	p40		\$20 \$20
en en	_65 ± 0.1			Θ	$ \phi$	
	*	80			10 ×	
54,		8	34		ו פרו	

Total No. of Pages: 4

[Contd...

Roll No.

Unit-II

2.	(a)		zgy used i	A 1712-
	9 9	chining. What is the advantages and limitations of thes	crecibods	com-
		pared to conventional machining.	e _ 0	6
	(b)	Explain electric discharge machining (EDM) process v	with neat si	cetch
		Discuss its advantages, limitations and application. W		
Ti.	50	by wide cut EDM?	n	10
1			**	M
	* v	Or		
2.	(a)	Discuss ultra sonic machining (USM) process with a	eat sketch.	Dis-
	CUS	the effect of frequency, amplitude, grain size, viscosify		
				8
	(b)	Explain following processes		
	(0)	Expansi following processes		
	16	(i) Plasma are machining		5
9	9. 5	GINU-t		~
		(ii) Hot machining		3
	20			
		Unit-III	0	
3.	(a)	Explain two wire method of effective diameter measure	ement of s	crew
	16	threads. Derive the formula for effective dies. What d	o you mea	m by
61		"Best-size" wire?		8
	(b)	Explain with neat sketch	45	e e
	(-)			
		(i) Gear tooth vernier caliper & its use		
	0s	(ii) Parkinson gear tester.		ø
		(-)	÷	
60		. Or	8	
	(a)	Sketch and explain any one instrument used for measu	t - £	
	(-)	surface roughness.	acabcar 01	8
	3947 X 2000 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			8
	(p)	Differentiate between a comparator and a measuring in		
		plain the working principle and applications of a pneum	ratic comp	
61		tor.	<i>55</i>	8
E3	0 51	2	Contd	ii.

	3	UBH-IV						
4.	(a)	Sketch a single point wetting tool showing all angles. What function of different angles? What is the optimum value of diangles while machining M.S. with H.S.S. tool?						
æ	(b)	A 6° back rake solid lathe tool is to be employed for the machinisteel at 50 m/min, feed 0.05 mm/rev. and at a depth of 2.0 mm maximum permissible deflection at the tool point is 0.01 mm are maximum allowable stress in the tool shank is 6 kg/mm ² . Fin cross section of a rectangular tool shank.						
		The cuetting force can be obtained from the formula	×					
		$F_c = 256x f^{0.18}xd$ (kg) and the work dia is 150mm.						
		Assume a rectanglan shank with H/B = 1.6 and tool overhand 1.25 H. Assume $E = 20 \times 10^3 \text{ kg/mm}^2$						
		Or	0					
4.	(a)	Explain different elements of a "plain milling cutter" with neat Discuss the functions of relief angle and rake angle.	sketch. 8					
	(b)	Disuses design of a milling cutter an following points:						
		(i) Size of cutter (ii) Tool angles						
te	×	(iii) Number of teeth (iv) Flutes, and	S.					
		(v) Material of cutter	8					
		Unit-V						
5	(a)	Discuss the materials and construction feature of lathe bed.	8					
	(b)	Discuss various stiffener arrangements for improving the stiffer lathe bed.	ness of					

Or

- (a) Explain different types of guide ways with neat ketches. Discuss about their materials also.
- (b) Explain Antifriction guide ways with neat sketch. What are their applicatios?

i e o geno o care e e o conista de eligibility de la eligibility de eligibility de la eligibility de eligibility de la eligibility de eligibilit

6E3051 4 [7650]